

FIG. 1




FIG. 2




FIG. 3A




FIG. 3B




FIG. 4




FIG. 5






FIG. 6A**FIG. 6B**

FIG. 7A




FIG. 7B




FIG. 7C






FIG. 8



102220" SEE 51660

FIG. 9



10/22/20" 5:22:51 PM

FIG. 10

URL

TROUBLE DB INPUT WINDOW

OCCURRENCE DATE ~1404

TYPE OF APPARATUS ~1401

OBJECT ~1403

APPARATUS S/N ~1402

DEGREE OF URGENCY ~1405

SYMPTOM ~1406


REMEDY ~1407

PROGRESS ~1408

1410 1411 1412

[LINK TO RESULT LIST DATABASE](#) [SOFTWARE LIBRARY](#) [OPERATION GUIDE](#)

091535 072701 102220 525F660

FIG. 11

SEMICONDUCTOR DEVICE MANUFACTURING FLOW

FIG. 12

